



City of Hyattsville
Hal Metzler
4633 Arundel Place
Hyattsville, MD 20781

Date: June 21, 2022

Bid # 3378

Precision Concrete Cutting

Jim Grimes

215 Middleboro Road

Wilmington DE 19804

jim@safesidewalksdemd.com

855-832-9876 office

302-250-5663 cell

888-622-0490 fax

Trip Hazards 3/8" and up

Property Address:

5100 Baltimore Avenue Hyattsville MD. 20781

Pin #	Height 1	Height 2	Lineal Ft	Location/Description	Severity	SQ FT
RHODE ISLAND AVENUE/BALTIMORE AVENUE						
22	0.625	0.000	5.00	5100 Baltimore Avenue, front center at door	Severe	25
23	0.500	0.000	6.00	5100 Baltimore Avenue, right of door	Hazardous	24
24	0.625	0.000	3.00	5100 Baltimore Avenue, right of door next	Severe	20
25	0.500	0.000	4.00	5132 Baltimore Avenue, front left adjacent to lamp post across	Hazardous	16
26	0.500	0.000	4.00	5132 Baltimore Avenue, front left adjacent to lamp post across next	Hazardous	16
27	0.625	0.000	8.00	5214 Baltimore Avenue, front left at lamp post m	Severe	64
28	0.750	0.000	7.00	5214 Baltimore Avenue, front left at storm drain	Critical	64
29	0.750	0.000	4.00	5214 Baltimore Avenue, front left at storm drain butterfly cut	Critical	64
30	1.000	0.000	4.00	5214 Baltimore Avenue, front left at storm drain butterfly cut	Critical	64
31	0.500	0.000	6.00	5214 Baltimore Avenue, front left at top of cross walk	Hazardous	36
32	0.375	0.000	6.00	5214 Baltimore Avenue, front left adjacent to cross walk next	Hazardous	64
33	0.500	0.000	2.00	5214 Baltimore Avenue, front left on crack at right of cross walk	Hazardous	36
34	0.500	0.125	5.00	5214 Baltimore Avenue, front left at right of cross walk next	Hazardous	25
35	0.625	0.125	5.00	5214 Baltimore Avenue, front left of door cross cut	Severe	40
36	0.500	0.250	5.00	5214 Baltimore Avenue, front center of door next, cross cut	Hazardous	40
37	0.500	0.375	5.00	5214 Baltimore Avenue, front right of door next, cross cut	Hazardous	
38	0.500	0.250	5.00	5214 Baltimore Avenue, front right of door next, cross cut	Hazardous	40
39	0.625	0.000	5.00	5214 Baltimore Avenue, front right of door, before lamp post next, cross cut	Severe	40
40	0.625	0.000	5.00	5214 Baltimore Avenue, front right of door, at lamp post next, cross cut	Severe	40
41	0.625	0.500	5.00	5214 Baltimore Avenue, front right of door, at lamp post next, cross cut	Severe	25
42	0.750	0.000	5.00	5214 Baltimore Avenue, front right at meter next, cross cut	Critical	25
43	0.375	0.000	8.00	5214 Baltimore Avenue, front right at meter same	Hazardous	64
44	0.500	0.000	3.00	5214 Baltimore Avenue, at right of steps, before Hamilionn Street	Hazardous	28
45	0.625	0.000	4.00	5214 Baltimore Avenue, across at left of ramp	Severe	36
46	0.500	0.000	4.00	5214 Baltimore Avenue, across at left of ramp by crack same	Hazardous	36

47	0.500	0.000	3.00	5214 Baltimore Avenue, across at crack on left of ramp next	Hazardous	36
48	0.500	0.000	3.00	5214 Baltimore Avenue, across at crack on right of ramp	Hazardous	36
49	0.500	0.375	5.00	5214 Baltimore Avenue, across adjacent to City of Hyattsville sign	Hazardous	25
50	0.500	0.000	4.00	5214 Baltimore Avenue, across adjacent to lamp post by City of Hyattsville sign	Hazardous	16
51	0.500	0.000	4.00	5214 Baltimore Avenue, across adjacent to telephone pole across	Hazardous	16
52	0.500	0.000	5.00	5214 Baltimore Avenue, across adjacent to sign across before lamp post	Hazardous	25
53	0.500	0.000	4.00	Baltimore Avenue, at cross path and camera	Hazardous	25
54	0.500	0.000	4.00	5200 Baltimore Avenue, across at left side of driveway	Hazardous	25
55	0.625	0.000	4.00	5200 Baltimore Avenue, across at right side of driveway	Severe	25
56	0.500	0.000	5.00	5123 Baltimore Avenue, front left at steps	Hazardous	25
57	1.500	1.000	5.00	5123 Baltimore Avenue, front left along steps cross cut	Critical	25
58	1.000	0.375	5.00	5123 Baltimore Avenue, front left along steps next, cross cut	Critical	40
59	0.750	0.000	4.00	5123 Baltimore Avenue, front left along steps next, cross cut	Critical	40
60	0.750	0.000	4.00	5123 Baltimore Avenue, front center at cross walk lamp post	Critical	40
61	0.500	0.000	4.00	5123 Baltimore Avenue, at left of cross walk butterfly cut	Hazardous	40
62	0.500	0.000	4.00	5123 Baltimore Avenue, at left of cross walk butterfly cut	Hazardous	40
63	0.375	0.000	5.00	5119 Baltimore Avenue, front right at window before door	Hazardous	25
64	0.500	0.000	5.00	5117 Baltimore Avenue, at left of door	Hazardous	25
65	0.500	0.000	6.00	5117 Baltimore Avenue, front right at parking meter	Hazardous	40
66	0.500	0.000	5.00	5101 Baltimore Avenue, front right at sign before lamp post	Hazardous	36
67	0.375	0.000	5.00	5100 Baltimore Avenue, across at telephone pole	Hazardous	25
68	0.625	0.000	5.00	5100 Baltimore Avenue, across at asphalt path	Severe	25
69	1.000	0.000	5.00	5100 Baltimore Avenue, across adjacent to lamp post	Critical	25
70	0.375	0.000	3.00	5100 Baltimore Avenue, across on crack at telephone pole	Hazardous	25
1	0.750	0.375	5.00	6038 Baltimore Ave front right at corner price sign past pole	Critical	20
2	0.875	0.000	3.00	6038 Baltimore Ave front right at manhole cover	Critical	20
3	0.500	0.250	5.00	6038 Baltimore Ave front right past 2nd pole	Hazardous	20
4	0.000	0.000	0.00	6038 Baltimore Ave front center driveway apron broken	Replace	
5	0.500	0.000	5.00	6038 Baltimore Ave front left past driveway before pole	Hazardous	20
6	0.500	0.000	4.00	6038 Baltimore Ave front left past pole	Hazardous	20
7	0.625	0.000	5.00	6034 Baltimore Ave front right at apron	Severe	20
8	0.500	0.000	3.00	6034 Baltimore Ave front center at pole	Hazardous	20
9	1.500	0.000	5.00	6030 Baltimore Ave front right past entrance	Critical	25
10	0.750	0.000	5.00	6030 Baltimore Ave front right past 1st pole at trees	Critical	20
11	0.375	0.250	5.00	6030 Baltimore Ave front center before speed limit sign	Hazardous	20
12	0.000	0.000	0.00	6030 Baltimore Ave front left panel broken before 3rd pole	Replace	
13	0.625	0.000	5.00	6030 Baltimore Ave front left past 3rd pole	Severe	20
14	0.625	0.000	2.00	6030 Baltimore Ave front left past 3rd pole	Severe	20
15	0.750	0.375	5.00	6030 Baltimore Ave front left past 3rd pole	Critical	20
16	0.500	0.250	8.00	5814 Baltimore Ave front right past crosswalk pole	Hazardous	64
17	0.375	0.000	3.00	5814 Baltimore Ave front left of door	Hazardous	25
18	0.875	0.375	3.00	5814 Baltimore Ave front left of door	Critical	15
19	0.500	0.375	5.00	5810 Baltimore Ave front right at door crack	Hazardous	20
20	0.500	0.375	3.00	5810 Baltimore Ave front right at door crack	Hazardous	15

21	1.875	0.750	3.00	5810 Baltimore Ave front left at storm drain	Critical	15
22	0.750	0.000	4.00	5810 Baltimore Ave front left at storm drain	Critical	25
23	0.000	0.000	0.00	5810 Baltimore Ave front left at storm drain	Replace	
24	0.500	0.375	4.00	5804 Baltimore Ave front right at lead to street past tree	Hazardous	24
25	0.500	0.375	4.00	5720 Baltimore Ave front left at lead to street before tree	Hazardous	24
26	0.500	0.375	4.00	5720 Baltimore Ave front left at lead to street past tree	Hazardous	24
27	0.750	0.000	10.00	5710 Baltimore Ave front right before storm drain	Critical	80
28	0.500	0.375	5.00	5710 Baltimore Ave front right of door	Hazardous	30
29	0.375	0.250	5.00	5710 Baltimore Ave front right of door	Hazardous	30
30	0.500	0.375	4.00	5710 Baltimore Ave front left of entrance at bicycle sign	Hazardous	20
31	0.375	0.250	5.00	5710 Baltimore Ave front left of entrance at bicycle sign	Hazardous	25
32	0.500	0.000	6.00	5702 Baltimore Ave front left at handicap ramp	Hazardous	24
33	0.375	0.000	4.00	5610 Baltimore Ave front left at window	Hazardous	16
34	0.375	0.000	4.00	5608 Baltimore Ave front left at window	Hazardous	16
35	0.375	0.375	4.00	5606 Baltimore Ave front left at bldg. corner	Hazardous	20
36	0.625	0.375	4.00	5604 Baltimore Ave front far right at courtyard	Severe	24
37	0.375	0.000	3.00	5604 Baltimore Ave front far right at courtyard	Hazardous	18
38	0.375	0.000	6.00	5602 Baltimore Ave front right of door	Hazardous	40
39	1.500	0.500	12.00	5600 Baltimore Ave front left at driveway	Critical	120
40	0.500	0.500	4.00	5600 Baltimore Ave front left at driveway crack	Hazardous	25
41	0.000	0.000	0.00	5504 Baltimore Ave front right panels heaved and broken	Replace	
42	0.625	0.500	4.00	5500 Baltimore Ave front center at center window	Severe	16
43	0.625	0.250	4.00	5500 Baltimore Ave front center at center window	Severe	16
44	1.625	1.250	10.00	5500 Baltimore Ave front left at manhole	Critical	60
45	1.875	0.000	6.00	5500 Baltimore Ave front left at manhole corner	Critical	36
46	1.000	0.000	6.00	5500 Baltimore Ave front left at mailbox	Critical	36
47	0.625	0.375	5.00	5326 Baltimore Ave front right past hydrant	Severe	20
48	0.000	0.000	0.00	5306 Baltimore Ave front left at storm drain panel broken	Replace	
49	0.750	0.000	2.00	Across 5214 Baltimore Ave past speed limit sign on bridge	Critical	8
50	0.375	0.375	2.00	Across 5214 Baltimore Ave past speed limit sign-on bridge	Hazardous	36
51	0.500	0.250	4.00	Across 4821A Baltimore Ave at cross walk post	Hazardous	16
52	0.625	0.375	5.00	4800 Baltimore Ave front left past manhole	Severe	25
53	0.625	0.000	3.00	Across 4729 Baltimore Ave past pole	Severe	25
54	0.500	0.000	3.00	Across 4723 Baltimore Ave before manhole	Hazardous	25
55	0.000	0.000	0.00	Across 4716 Baltimore Ave front right concrete broken	Replace	
56	0.750	0.250	8.00	4644 Baltimore Ave Citco driveway apron before manhole	Critical	48
57	0.375	0.000	3.00	4623 Baltimore Ave front left edge of driveway	Hazardous	20
58	0.375	0.000	2.00	4623 Baltimore Ave front far left before hydrant	Hazardous	16
59	0.500	0.000	4.00	4623 Baltimore Ave front far left at pole near corner	Hazardous	16
60	0.625	0.500	5.00	4643 Baltimore Ave front right at driveway edge crack	Severe	25
61	0.625	0.500	5.00	4643 Baltimore Ave front center driveway edge	Severe	25
62	0.750	0.375	5.00	4729 Baltimore Ave front right of lead walk	Critical	30
63	1.000	0.000	5.00	4801 Baltimore Ave front right at manhole	Critical	40
64	0.375	0.375	5.00	4821A Baltimore Ave front right at sign	Hazardous	25
65	0.500	0.000	4.00	5221 Baltimore Ave front right before brick walkway	Hazardous	25
66	0.500	0.000	5.00	5221 Baltimore Ave front left of door	Hazardous	36
67	0.500	0.000	4.00	5301 Baltimore Ave at lead walk	Hazardous	20
68	1.000	0.000	4.00	5303 Baltimore Ave front left past window	Critical	30
69	0.750	0.000	7.00	5305 Baltimore Ave right of door	Critical	35

70	1.125	0.875	4.00	5331 Baltimore Ave left of suite 103 at lead walk to street	Critical	24
71	0.750	0.000	2.00	5501 Baltimore Ave across from suite 103	Critical	12
72	0.875	0.625	5.00	5501 Baltimore Ave left of suite 101 Chipotle	Critical	25
73	0.625	0.625	5.00	5501 Baltimore Ave left of suite 101 Chipotle	Severe	25
74	0.750	0.000	5.00	5501 Baltimore Ave suite 600 FedEx left of entrance	Critical	25
75	0.875	0.000	5.00	5501 Baltimore Ave suite 600 FedEx front left past bldg. corner	Critical	20
76	0.625	0.250	5.00	5609 Baltimore Ave front right driveway	Severe	30
77	0.000	0.000	0.00	4501 Longfellow St right side, side walk to street sunken past bench	Replace	
78	0.625	0.375	4.00	4501 Longfellow St right side at tree	Severe	24
79	0.750	0.500	4.00	5705 Baltimore Ave top of handicap at light pole	Critical	25
80	0.750	0.500	5.00	5705 Baltimore Ave top of handicap	Critical	25
81	0.500	0.000	4.00	5705 Baltimore Ave top of handicap left side	Hazardous	25
82	0.500	0.000	5.00	5705 Baltimore Ave front right before entrance to fitness center	Hazardous	25
83	0.500	0.000	5.00	5705 Baltimore Ave front left of entrance to 104	Hazardous	25
84	0.500	0.250	5.00	5711 Baltimore Ave front right of steps	Hazardous	25
85	0.000	0.000	0.00	5731 Baltimore Ave multiple panels heaved	Replace	
86	0.500	0.250	4.00	5801 Baltimore Ave front right driveway edge	Hazardous	20
87	0.750	0.375	4.00	5801 Baltimore Ave left driveway edge	Critical	20
88	1.000	0.000	4.00	5803 Baltimore Ave right driveway edge	Critical	20
89	1.000	0.000	4.00	5811 Baltimore Ave front right driveway edge	Critical	20
90	0.500	0.000	5.00	5817 Baltimore Ave front right driveway	Hazardous	50
91	0.500	0.000	3.00	5817 Baltimore Ave front center at window	Hazardous	16
92	0.500	0.000	4.00	6001 Baltimore Ave front right past post	Hazardous	20
93	0.750	0.000	5.00	6009 Baltimore Ave front right driveway edge	Critical	20
94	0.500	0.000	4.00	6009 Baltimore Ave front right driveway edge past hydrant	Hazardous	20
95	1.250	0.750	4.00	6009 Baltimore Ave front right left driveway edge	Critical	20
96	0.625	0.000	4.00	6009 Baltimore Ave front right driveway edge	Severe	50
97	0.625	0.000	5.00	6019 Baltimore Ave front far left before lot sign	Severe	25
98	1.375	1.250	5.00	6033 Baltimore Ave front right driveway edge	Critical	25
99	0.625	0.375	4.00	6033 Baltimore Ave front right left driveway edge	Severe	20
100	0.375	0.000	4.00	6033 Baltimore Ave front center at door	Hazardous	16
101	0.625	0.500	5.00	6035 Baltimore Ave front left at sign	Severe	25
Totals:			654			4073
TOTAL REPAIRS TO BE MADE BY PRECISION CONCRETE CUTTING FOR BALTIMORE AVENUE:						142
TOTAL FOR SIDEWALK TRIP HAZARD REPAIR:						\$9,230.00

The information in this bid is confidential, and is to be used only by the intended recipient and Precision Concrete Cutting in evaluating the project. Any copying or unauthorized disclosure of this information is prohibited.

©Precision Concrete Cutting of Delaware and Maryland, Inc.

PRECISION CONCRETE CUTTING DOES NOT REMOVE AND REPLACE SIDEWALK PANELS.

THIS BID IS VALID FOR 90 DAYS.