



City of Hyattsville
Hal Metzler
4633 Arundel Place
Hyattsville, MD 20781

Revised Date: July 5, 2022

Bid # 3381
Revisions per Hal Metzler

Trip Hazards 3/8" and up

Precision Concrete Cutting

Jim Grimes
215 Middleboro Road
Wilmington DE 19804

jim@safesidewalksdemd.com

855-832-9876 office
302-250-5663 cell
888-622-0490 fax

Property Address:

3790 East West Highway Hyattsville MD. 20781

Pin #	Height 1	Height 2	Lineal Ft	Location/Description	Severity	SQ FT
Adelphi Road						
230	0.375	0.250	8.00	Adelphi Road, past cross street of University Boulevard, adjacent to telephone pole across	Hazardous	40
231	0.000	0.000	0.00	Adelphi Road, adjacent to telephone pole in yard replace 6 broken panels	Replace	
232	0.375	0.000	6.00	Adelphi Road, at telephone pole before signs	Hazardous	40
233	0.000	0.000	0.00	Adelphi Road, replace 2 panels past telephone between signs	Replace	
234	0.000	0.000	0.00	Adelphi Road, replace 3 panels at Event Parking signs	Replace	
235	0.000	0.000	0.00	Adelphi Road, replace 4 panels at telephone pole wires	Replace	
236	0.750	0.000	6.00	Adelphi Road, past telephone pole, on crack at storm drain	Critical	40
237	0.500	0.000	5.00	Adelphi Road, past telephone pole, along top of storm drain	Hazardous	30
238	0.500	0.125	4.00	Adelphi Road, at telephone pole past cross street of Campus Drive	Hazardous	16
239	0.375	0.000	4.00	Adelphi Road, past telephone pole adjacent to lamp post across	Hazardous	16
240	0.625	0.000	7.00	7703 Adelphi Road, front right along top of storm drain	Severe	40
241	1.125	0.500	4.00	7703 Adelphi Road, front right past storm drain on edge of driveway	Critical	24
242	0.500	0.000	4.00	7601 Adelphi Road, front left at property line	Hazardous	16
243	0.625	0.000	4.00	7601 Adelphi Road, at right side of driveway	Severe	16
244	0.500	0.000	4.00	Adelphi Road, at bus stop sign	Hazardous	16
245	0.625	0.250	4.00	Adelphi Road, past No Parking sign before telephone pole	Severe	16
246	0.375	0.000	4.00	Adelphi Road, past No Parking sign at telephone pole	Hazardous	16
247	0.750	0.500	4.00	Adelphi Road, past Do Not Enter sign, before tree stump	Critical	16
248	0.500	0.000	4.00	Adelphi Road, past bus stop sign F6 F8, by bench	Hazardous	16
249	0.625	0.000	4.00	Adelphi Road, past path towards church, at top of ramp	Severe	16
250	0.375	0.000	4.00	7311 Adelphi Road, front left at property line	Hazardous	16
251	0.375	0.250	4.00	7311 Adelphi Road, at left side of driveway	Hazardous	16
252	0.375	0.250	4.00	7305 Adelphi Road, at right side of driveway	Hazardous	16
253	0.500	0.375	4.00	7305 Adelphi Road, front right at tree in yard	Hazardous	16
254	0.875	0.000	4.00	7217 Adelphi Road, front left on water meter cover	Critical	16

255	0.000	0.000	0.00	7217 Adelphi Road, front left replace 1 broken panel at driveway	Replace	
256	0.625	0.125	4.00	7217 Adelphi Road, at right side of driveway	Severe	16
257	0.875	0.500	4.00	7215 Adelphi Road, at left side of driveway	Critical	16
258	0.500	0.000	4.00	7213 Adelphi Road, on left side of driveway	Hazardous	16
259	0.750	0.000	4.00	7211 Adelphi Road, at water meter cover on driveway	Critical	16
260	0.375	0.000	4.00	7211 Adelphi Road, at right side of driveway	Hazardous	16
261	0.375	0.000	5.00	7209 Adelphi Road, at right side of driveway	Hazardous	25
262	0.375	0.000	4.00	7207 Adelphi Road, front left at window	Hazardous	16
263	0.375	0.125	4.00	7207 Adelphi Road, at left side of driveway	Hazardous	16
264	0.750	0.375	4.00	7207 Adelphi Road, at right side of driveway	Critical	16
265	0.625	0.250	4.00	7205 Adelphi Road, front right	Severe	16
266	0.375	0.000	4.00	7205 Adelphi Road, at left side of driveway	Hazardous	16
267	0.500	0.250	4.00	7201 Adelphi Road, front left at bus stop sign	Hazardous	16
268	0.750	0.000	4.00	7201 Adelphi Road, front left at bus stop	Critical	16
269	0.500	0.375	4.00	Adelphi Road, past cross street of Wells Parkway, at bush before signs	Hazardous	16
270	0.375	0.000	4.00	Adelphi Road, past cross street to Wells Parkway, past bush at telephone pole	Hazardous	16
271	0.625	0.250	4.00	Adelphi Road, past telephone pole at sign	Severe	16
272	0.500	0.000	4.00	Adelphi Road, past green drain cover in grass, before sign	Hazardous	16
273	1.125	0.625	4.00	7103 Adelphi Road, at left side of driveway	Critical	16
274	0.500	0.375	4.00	7103 Adelphi Road, at right side of driveway	Hazardous	16
275	0.375	0.250	4.00	7101 Adelphi Road, front left at fire hydrant	Hazardous	16
276	0.750	0.500	4.00	7101 Adelphi Road, at left side of driveway	Critical	16
277	0.625	0.000	4.00	7019 Adelphi Road, at right side of driveway	Severe	16
278	0.500	0.000	2.00	Adelphi Road, past sign, before storm drain cover butterfly cut	Hazardous	16
279	0.375	0.000	2.00	Adelphi Road, past sign, before storm drain cover butterfly cut	Hazardous	16
280	0.625	0.000	3.00	Adelphi Road, past sign, at storm drain cover	Severe	16
281	0.500	0.000	4.00	Adelphi Road, past storm drain cover before sign	Hazardous	16
282	0.375	0.000	4.00	Adelphi Road, past End School sign, before tree in yard	Hazardous	16
283	0.375	0.000	4.00	Adelphi Road, past End School sign, at tree in yard	Hazardous	16
284	0.375	0.000	4.00	Adelphi Road, past tree and sign, at edge of driveway	Hazardous	16
285	0.375	0.125	4.00	Adelphi Road, past driveway at trees in yard, before storm drain cover	Hazardous	16
286	0.500	0.125	4.00	Adelphi Road, past trees in yard, at storm drain cover	Hazardous	16
287	1.000	0.750	4.00	7011 Adelphi Road, at left side of driveway	Critical	16
288	0.500	0.000	4.00	7011 Adelphi Road, front right at trees in yard, before telephone pole	Hazardous	16
289	0.625	0.000	5.00	7009 Adelphi Road, front left on storm drain cover	Severe	25
290	0.500	0.000	4.00	7009 Adelphi Road, at left side of driveway	Hazardous	16
291	0.750	0.500	4.00	7009 Adelphi Road, at right side of driveway	Critical	16
292	0.500	0.000	4.00	7009 Adelphi Road, front right	Hazardous	16
293	0.625	0.000	4.00	7009 Adelphi Road, front right before camera	Severe	16
294	0.625	0.250	4.00	7007 Adelphi Road, at left side of driveway	Severe	16
295	0.375	0.000	4.00	7007 Adelphi Road, on left side of driveway	Hazardous	16
296	0.500	0.000	2.00	7007 Adelphi Road, on right side of driveway butterfly cut	Hazardous	16

297	0.500	0.000	2.00	7007 Adelphi Road, at right side of driveway butterfly cut	Hazardous	16
298	0.375	0.375	4.00	7005 Adelphi Road, front left at tree in yard	Hazardous	16
299	1.125	0.750	4.00	7005 Adelphi Road, front center	Critical	16
300	0.750	0.375	4.00	7005 Adelphi Road, front right at tree	Critical	16
301	0.500	0.000	4.00	7003 Adelphi Road, front right at tree	Hazardous	16
302	0.375	0.250	4.00	7003 Adelphi Road, at right side of driveway	Hazardous	16
303	0.500	0.000	3.00	Adelphi Road, at right side of driveway before tree	Hazardous	16
304	0.375	0.000	2.00	Adelphi Road, past driveway, at tree butterfly cut	Hazardous	16
305	0.500	0.000	2.00	Adelphi Road, past driveway, at tree butterfly cut	Hazardous	16
306	0.375	0.000	4.00	Adelphi Road, past bus stop, at tree	Hazardous	16
307	0.500	0.375	4.00	Adelphi Road, past telephone pole at tree	Hazardous	16
308	0.500	0.250	4.00	6909 Adelphi Road, front left before driveway	Hazardous	16
309	1.500	0.500	4.00	6909 Adelphi Road, at right side of driveway	Critical	16
310	1.250	0.000	4.00	6909 Adelphi Road, front left at tree	Critical	16
311	1.500	0.000	4.00	6909 Adelphi Road, front left at tree next	Critical	16
312	0.750	0.500	4.00	6907 Adelphi Road, at right side of driveway	Critical	16
313	0.500	0.000	2.00	6907 Adelphi Road, front right at sign butterfly cut	Hazardous	16
314	0.500	0.000	2.00	6907 Adelphi Road, front right at sign butterfly cut	Hazardous	16
315	0.500	0.375	4.00	6905 Adelphi Road, right of lead walk	Hazardous	16
316	0.625	0.375	4.00	6903 Adelphi Road, at left side of driveway	Severe	16
317	0.750	0.375	4.00	6903 Adelphi Road, front right at tree	Critical	16
318	0.375	0.000	4.00	Adelphi Road, past cross street of Underwood, by trash can before tree	Hazardous	16
319	0.500	0.000	4.00	Adelphi Road, past trash can, at tree before signs	Hazardous	16
320	0.625	0.375	4.00	6811 Adelphi Road, on left side of driveway	Severe	16
321	0.625	0.500	4.00	6811 Adelphi Road, front right at small tree	Severe	16
322	0.375	0.000	4.00	6809 Adelphi Road, at lead walk	Hazardous	16
323	0.625	0.250	4.00	6809 Adelphi Road, front right	Severe	16
324	0.500	0.000	4.00	6809 Adelphi Road, front right at tree	Hazardous	16
325	0.625	0.250	4.00	6809 Adelphi Road, front right before driveway	Severe	16
326	0.500	0.375	4.00	6807 Adelphi Road, at right side of driveway	Hazardous	16
327	0.875	0.000	4.00	6807 Adelphi Road, at left of lead walk	Critical	16
328	0.625	0.000	4.00	6807 Adelphi Road, at right of lead walk	Severe	16
329	0.500	0.375	4.00	6807 Adelphi Road, front right at bushes in yard	Hazardous	16
330	0.625	0.000	4.00	6807 Adelphi Road, front right before telephone pole	Severe	16
331	0.625	0.000	4.00	6805 Adelphi Road, at left side of driveway	Severe	16
332	0.500	0.000	4.00	6805 Adelphi Road, front center	Hazardous	16
333	0.375	0.000	4.00	6805 Adelphi Road, front right	Hazardous	16
334	0.875	0.500	4.00	6803 Adelphi Road, at left side of driveway	Critical	16
335	0.500	0.125	4.00	6803 Adelphi Road, at right side of driveway	Hazardous	16
336	1.250	1.000	4.00	6801 Adelphi Road, front left	Critical	16
337	1.500	0.250	4.00	6801 Adelphi Road, front right at tree	Critical	16
338	0.500	0.000	4.00	6715 Adelphi Road, front left between tree and sign	Hazardous	16
339	0.000	0.000	0.00	6715 Adelphi Road, front right replace 1 broken panel	Replace	
340	1.125	0.625	4.00	6715 Adelphi Road, at left side of driveway	Critical	16
341	1.500	1.500	4.00	6713 Adelphi Road, at lead walk	Critical	16
342	0.625	0.000	4.00	6713 Adelphi Road, front right on crack at tree	Severe	16
343	0.750	0.000	4.00	6711 Adelphi Road, at left side of driveway	Critical	16
344	0.500	0.000	2.00	6711 Adelphi Road, on crack at right side of driveway	Hazardous	16

345	0.375	0.000	3.00	6711 Adelphi Road, front left on crack	Hazardous	16
346	0.375	0.000	4.00	6711 Adelphi Road, right of lead walk	Hazardous	16
347	0.375	0.000	4.00	6711 Adelphi Road, right of lead walk same	Hazardous	16
348	0.500	0.375	4.00	6711 Adelphi Road, front right by water drain cover in grass	Hazardous	16
349	0.375	0.000	2.00	6711 Adelphi Road, front right at drain spout butterfly cut	Hazardous	16
350	0.750	0.000	2.00	6711 Adelphi Road, front right at drain spout butterfly cut	Critical	16
351	1.500	0.500	4.00	6709 Adelphi Road, at left side of driveway	Critical	16
352	0.625	0.375	4.00	6709 Adelphi Road, at right side of driveway	Severe	16
353	0.375	0.000	2.00	6709 Adelphi Road, front right butterfly cut	Hazardous	16
354	0.375	0.000	2.00	6709 Adelphi Road, front right butterfly cut	Hazardous	16
355	0.625	0.000	4.00	6709 Adelphi Road, front right	Severe	16
356	0.500	0.375	4.00	6707 Adelphi Road, on left side of driveway	Hazardous	16
357	0.375	0.000	4.00	6707 Adelphi Road, left of lead walk	Hazardous	16
358	0.625	0.375	4.00	6707 Adelphi Road, right of lead walk	Severe	16
359	0.500	0.125	4.00	6707 Adelphi Road, front right at tree by house	Hazardous	16
360	0.375	0.250	4.00	6705 Adelphi Road, at left side of driveway	Hazardous	16
361	0.625	0.500	4.00	6703 Adelphi Road, at left side of driveway	Severe	16
362	0.500	0.125	4.00	6703 Adelphi Road, on left side of driveway	Hazardous	16
363	1.125	0.750	4.00	6703 Adelphi Road, left of lead walk	Critical	16
364	0.875	0.000	4.00	6703 Adelphi Road, front right at tree	Critical	16
365	0.500	0.375	4.00	6703 Adelphi Road, front right at property line	Hazardous	16
366	1.125	0.125	4.00	6701 Adelphi Road, front left past telephone pole, at edge of driveway and fence	Critical	16
367	0.375	0.250	4.00	6701 Adelphi Road, at left side of driveway	Hazardous	16
368	0.625	0.250	4.00	6701 Adelphi Road, on right side of driveway	Severe	16
369	0.500	0.000	5.00	Adelphi Road, at right side of ramp on cross street of Beechwood Road	Hazardous	25
370	0.500	0.250	4.00	Adelphi Road, past cross street of Beechwood Road, adjacent to telephone pole across	Hazardous	16
371	0.375	0.000	4.00	Adelphi Road, past telephone pole adjacent to sign in middle	Hazardous	16
372	0.625	0.500	4.00	Adelphi Road, past No Parking sign, before driveway	Severe	16
373	1.125	0.000	4.00	Adelphi Road, past No Parking sign, on right side of driveway	Critical	16
374	0.500	0.375	4.00	Adelphi Road, past driveway adjacent to tree in yard before sign	Hazardous	16
375	0.375	0.000	4.00	Adelphi Road, past bike sign at tree	Hazardous	16
376	1.250	1.000	4.00	6600 Adelphi Road, across at tree past bus stop	Critical	16
377	0.375	0.000	4.00	6600 Adelphi Road, across at tree before sign	Hazardous	16
378	0.375	0.000	4.00	6600 Adelphi Road, across past sign adjacent to University Park sign	Hazardous	16
379	0.750	0.000	4.00	6600 Adelphi Road, across past University Park sign at tree before fire hydrant	Critical	16
380	0.500	0.375	4.00	6600 Adelphi Road, across past fire hydrant, before telephone pole	Hazardous	16
381	1.875	1.250	4.00	Adelphi Road, at sign past cross walk	Critical	16
382	0.500	0.125	4.00	6519 Adelphi Road, front left at telephone pole	Hazardous	16
383	0.500	0.125	4.00	6519 Adelphi Road, front right at property line	Hazardous	16
384	0.375	0.000	4.00	6515 Adelphi Road, at lead walk	Hazardous	16
385	0.500	0.000	4.00	6515 Adelphi Road, front right	Hazardous	16
386	0.375	0.125	4.00	6513 Adelphi Road, right of lead walk	Hazardous	16

387	0.375	0.000	4.00	6513 Adelphi Road, front right	Hazardous	16
388	0.875	0.500	4.00	6511 Adelphi Road, front right	Critical	16
389	0.750	0.500	4.00	6507 Adelphi Road, front left at telephone pole	Critical	16
390	0.500	0.000	4.00	6505 Adelphi Road, at right side of lead walk	Hazardous	16
391	0.375	0.125	4.00	6505 Adelphi Road, front right at drain spout	Hazardous	16
392	0.500	0.375	4.00	6505 Adelphi Road, front right before telephone pole	Hazardous	16
393	0.625	0.250	4.00	6501 Adelphi Road, at left side of lead walk	Severe	16
394	0.625	0.000	5.00	6427 Adelphi Road, front left at top side of ramp	Severe	25
395	0.375	0.000	4.00	6427 Adelphi Road, at right side of lead walk	Hazardous	16
396	0.500	0.250	4.00	6423 Adelphi Road, front right at window	Hazardous	16
397	0.500	0.000	4.00	6421 Adelphi Road, at left side of lead walk	Hazardous	16
398	0.500	0.375	4.00	6419 Adelphi Road, front right on crack at sign	Hazardous	16
399	0.375	0.000	4.00	6417 Adelphi Road, front right at trees in yard	Hazardous	16
400	0.375	0.000	4.00	6413 Adelphi Road, front left at drain spout	Hazardous	16
401	0.375	0.000	4.00	6413 Adelphi Road, front center	Hazardous	16
402	0.750	0.000	4.00	Adelphi Road, at Adopt A Road sign before driveway edge	Critical	16
403	0.875	0.000	4.00	Adelphi Road, past Adopt A Road sign, on left driveway edge	Critical	16
Totals:			659			2842
TOTAL REPAIRS TO BE MADE BY PRECISION CONCRETE CUTTING FOR ADELPHI ROAD AREA:						168
TOTAL FOR SIDEWALK TRIP HAZARD REPAIR:						\$10,920.00

The information in this bid is confidential, and is to be used only by the intended recipient and Precision Concrete Cutting in evaluating the project. Any copying or unauthorized disclosure of this information is prohibited.

©Precision Concrete Cutting of Delaware and Maryland, Inc.

PRECISION CONCRETE CUTTING DOES NOT REMOVE AND REPLACE SIDEWALK PANELS.

THIS BID IS VALID FOR 90 DAYS.