



**City of Hyattsville**  
Hal Metzler  
4633 Arundel Place  
Hyattsville, MD 20781

**Date: June 21, 2022**

**Bid # 3380**

**Trip Hazards 3/8" and up**

**Precision Concrete Cutting**

Jim Grimes

215 Middleboro Road

Wilmington DE 19804

[jim@safesidewalksdemd.com](mailto:jim@safesidewalksdemd.com)

855-832-9876 office

302-250-5663 cell

888-622-0490 fax

**Property Address:**

2903 Hamilton Street Hyattsville MD. 20781

Pin #	Height 1	Height 2	Lineal Ft	Location/Description	Severity	SQ FT
<b>Hamilton Street</b>						
1	0.500	0.000	4.00	2903 Hamilton St front left at bldg. corner	Hazardous	25
2	1.000	0.000	5.00	5398 Hamilton St Food Mart front left bottom of handicap ramp	Critical	25
3	0.500	0.000	4.00	5398 Hamilton St Food Mart front far left at corner area	Hazardous	16
4	0.500	0.000	5.00	3505 Hamilton St front right before pole	Hazardous	25
5	0.750	0.000	5.00	3505 Hamilton St front right before pole	Critical	25
6	0.750	0.000	5.00	3505 Hamilton St front left before pole at corner	Critical	25
7	0.625	0.000	5.00	3505 Hamilton St front left before pole at corner	Severe	25
8	1.250	0.500	4.00	3511 Hamilton St Bestway front left bottom of handicap ramp	Critical	24
9	0.750	0.000	4.00	3511 Hamilton St Bestway front far left at mailbox	Critical	16
10	0.500	0.000	5.00	3601 Hamilton St front center at lead walk	Hazardous	48
11	0.500	0.250	4.00	3609 Hamilton St front left past driveway	Hazardous	16
12	0.750	0.000	2.00	3900 Hamilton St front right of park at light post before bench	Critical	25
13	0.750	0.000	2.00	3900 Hamilton St front center of park past driveway at storm drain	Critical	10
14	0.750	0.000	2.00	3900 Hamilton St front center of park past driveway at storm drain	Critical	10
15	0.500	0.250	4.00	Across 4012 Hamilton St at no parking sign	Hazardous	16
16	0.500	0.000	4.00	4107 Hamilton St front right at pole	Hazardous	16
17	0.500	0.375	4.00	4113 Hamilton St front center past stairs	Hazardous	16
18	0.500	0.375	4.00	4115 Hamilton St front center before stairs	Hazardous	16
19	0.750	0.250	4.00	4115 Hamilton St front center past stairs	Critical	16
20	0.750	0.000	4.00	Across 4116 Hamilton St driveway past tree	Critical	16
21	0.625	0.000	4.00	Across 4116 Hamilton St at red shed	Severe	16
22	0.500	0.375	5.00	4302 Hamilton St front entrance	Hazardous	20
23	0.625	0.000	5.00	4307 Hamilton St front right past sign	Severe	25
24	1.125	0.000	4.00	4307 Hamilton St front right past tree	Critical	16
25	0.500	0.000	4.00	4309 Hamilton St front right at stone wall	Hazardous	16
26	0.750	0.000	4.00	4313 Hamilton St front right at downspout	Critical	16

27	1.000	0.000	5.00	Across 4320 Hamilton St at post and drain	Critical	56
28	1.000	0.000	5.00	Across 4320 Hamilton St at storm drain and do not enter sign	Critical	25
29	1.500	0.000	6.00	Across 4320 Hamilton St at storm drain and do not enter sign	Critical	30
30	0.750	0.000	6.00	Across 4320 Hamilton St past storm drain	Critical	30
31	0.750	0.375	4.00	4306 Hamilton St front far right at pay booth	Critical	16
32	1.000	0.000	4.00	4306 Hamilton St front far right at pay booth	Critical	16
33	0.500	0.000	4.00	4306 Hamilton St front far left at corner	Hazardous	16
34	0.625	0.250	4.00	4112 Hamilton St front left at water meter	Severe	16
35	0.625	0.000	4.00	4112 Hamilton St front left at storm drain	Severe	16
36	0.500	0.000	3.00	4100 Hamilton St front right of stairs	Hazardous	16
37	0.500	0.000	4.00	4034 Hamilton St front at stairs	Hazardous	16
38	0.375	0.000	4.00	4020 Hamilton St front left before driveway	Hazardous	16
39	0.500	0.000	3.00	4018 Hamilton St front left before driveway	Hazardous	16
40	0.625	0.000	5.00	3900 Hamilton St Prince George Apts front center at storm drain adj to property sign	Severe	25
41	0.625	0.000	4.00	3806 Hamilton St Castle Manor Apts front left of entrance before tree	Severe	16
42	1.750	0.000	3.00	3806 Hamilton St Castle Manor Apts front left at tree	Critical	16
43	0.625	0.000	4.00	3802 Hamilton St Castle Manor Apts front left at tree	Severe	16
44	2.000	2.000	3.50	3800 Hamilton St Castle Manor Apts front right at tree	Critical	16
45	0.625	0.000	2.00	3710 Hamilton St front left of driveway	Severe	16
46	0.500	0.250	4.00	3708 Hamilton St front right of driveway	Hazardous	16
47	0.500	0.250	4.00	3706 Hamilton St front left of lead walk	Hazardous	16
48	0.625	0.250	4.00	3702 Hamilton St front right at driveway	Severe	16
49	0.500	0.000	2.00	3702 Hamilton St front left at pole	Severe	16
50	0.500	0.000	2.00	3702 Hamilton St front left at pole	Hazardous	16
51	0.500	0.000	3.00	3702 Hamilton St front left past pole	Hazardous	16
52	0.625	0.000	4.00	3614 Hamilton St front right at tree	Severe	16
53	0.875	0.000	4.00	3614 Hamilton St front left of lead walk	Critical	16
54	0.000	0.000	0.00	3614 Hamilton St front left at tree panel heaved	Replace	
55	0.500	0.000	4.00	3610 Hamilton St front right at tree	Hazardous	16
56	0.500	0.000	3.00	3512 Hamilton St across Bestway before park entrance at manhole	Hazardous	25
57	1.000	0.500	6.00	3430 Hamilton St front right at corner	Critical	25
58	0.500	0.000	3.00	3430 Hamilton St front right at hydrant	Hazardous	16
59	0.500	0.000	2.00	3430 Hamilton St front left of lead walk	Hazardous	16
60	0.625	0.000	3.00	3430 Hamilton St front left at driveway	Severe	16
61	0.625	0.000	4.00	3430 Hamilton St front left at driveway	Severe	16
62	0.500	0.000	3.00	3430 Hamilton St front left past driveway	Hazardous	16
<b>Totals:</b>			<b>239</b>			<b>1184</b>
<b>TOTAL REPAIRS TO BE MADE BY PRECISION CONCRETE CUTTING FOR HAMILTON STREET AREA:</b>						<b>61</b>
<b>TOTAL FOR SIDEWALK TRIP HAZARD REPAIR:</b>						<b>\$3,965.00</b>

The information in this bid is confidential, and is to be used only by the intended recipient and Precision Concrete Cutting in evaluating the project. Any copying or unauthorized disclosure of this information is prohibited.

©Precision Concrete Cutting of Delaware and Maryland, Inc.

PRECISION CONCRETE CUTTING DOES NOT REMOVE AND REPLACE SIDEWALK PANELS.

**THIS BID IS VALID FOR 90 DAYS.**